

BOABC VANCOUVER ISLAND NORTH ZONE MEETING AGENDA

Time: 1:00pm – 4:00pm Date: February 2, 2023

Living and working with gratitude and respect on the ancestral, unceded, and un-surrendered territories of Indigenous peoples in British Columbia.

# (1) CALL TO ORDER

I would like to begin by acknowledging the ancestral, traditional, and unceded territories of Indigenous peoples in British Columbia, on whose territory we are today.

(Colin)

# (2) GUESTS (no motion required)

- Noah Quastel, Director, Law and Policy, Healthy Indoor Environments, BC Lung Foundation
- Dr. Anne-Marie Nicol, Associate Professor, Faculty of Health Sciences, Simon Fraser University
- Joel Hamilton, Home Partners Program Provincial Coordinator, FireSmart BC
- Tyler Wightman, Executive Director & Registrar, BOABC

(3)	AGENDA (requires motion to adopt)	(Colin)
(4)	PREVIOUS MINUTES (requires motion to adopt)	(Colin)
(5)	NEW BUSINESS (no motion required)	(Colin)
	<ul> <li>5.1 Radon and the BC Building Code: Assessing Implementation</li> <li>Noah Quastel</li> <li>Dr. Anne-Marie Nicol</li> </ul>	
	5.2 FireSmart BC & Deep Dive into the Home Ignition Zone - Joel Hamilton	
	5.3 Zone Director/Alternate Zone Director Nominations	(Tony)
	5.4 What to Expect from BOABC in 2023 - Tyler Wightman	
(6)	STANDING AGENDA ITEMS (no motion required)	(Colin)
	Building Officials' Association of BC Suite 224, 186 – 8120 No. 2 Road, Richmond, BC V7C 5J8	

604-270-9516 / info@boabc.org www.boabc.org



## 6.1 BOABC Calendar of Events

- CPD Offering Energy Step Code Training
- CPD Offering Reducing Warranty Claims
- CPD Offering Building Envelope Course
- CPD Offering Primary Changes to the 2020 National Model Codes
- BOABC Spring Conference & AGM, Richmond, BC, May 28-31, 2023

### 6.2 <u>BC Appeal Board Rulings</u>

- Appeal 1878 Exposure Protection for Required Egress Door Exterior Path of Travel, February 17, 2022
- <u>Appeal 1880</u> Required guard protection at intersection of deck and sloped roof, February 17, 2022
- <u>Appeal 1882</u> Minimum Room Size for a Water-Closet Room (Powder Room), March 17, 2022
- <u>Appeal 1883</u> Minimum Doorway Size for Water-Closet Room (Powder Room), March 17, 2022
- <u>Appeal 1884</u> Reduction of required doorway width and obstruction of access to the doorway March 17, 2022
- Appeal 1885 Application of Building Code for Fabric Cover Yurts, April 28, 2022
- Appeal 1886 Location of Required Water Closets, April 28, 2022
- <u>Appeal 1887</u> Continuity of Required Fire Separation for a Secondary Suite, April 28, 2022
- Appeal 1890 Attic Access for Self-Storage Units, June 16, 2022
- Appeal 1892 Fire Extinguishing for a Distillery, August 18, 2022
- Appeal 1893 Required Fire Blocking, July 21, 2022
- Appeal 1894 Source of Water Supply for NFPA 13 Sprinkler Requirements, September 15, 2022
- Appeal 1895 Use of Long Sweep degree Elbows in a Sanitary Drainage System, August 18, 2022
- Appeal 1896 Required Fire Blocking, September 15, 2022

### 6.3 **<u>BC Building Code Interpretations</u>**

- 18-0196 Connection of Sewage Sump Vent to Other Pipes in a Venting System
- 18-0197 Vents for Oil Interceptors Connected to a Storm Drainage System
- 18-0199 Structural Design of Guards in Part 9 Buildings
- 18-0200 Positioning of Bottom Edge of Vision Panel at Doors
- 18-0201 Wireless Interconnection of Smoke Alarms
- 18-0202 Spiral Stair for Basement Storage Unit
- 18-0203 Ramp Design
- 18-0206 Permanent Label
- 18-0207 Exit Exposure Protection Without a Stair or Ramp
- 18-0209 Rainwater Leaders Connecting to a Dry Well

Building Officials' Association of BC

Suite 224, 186 – 8120 No. 2 Road, Richmond, BC V7C 5J8

604-270-9516 / info@boabc.org

www.boabc.org



\_

- 18-0210 Fire Blocks in Walls with Minor Combustible Components
- 18-0213 Membrane Ceiling used as a Fire Separation
- 18-0215 Exit Width Reduction at Door Swings
- 18-0216 Occupant Load of Residential Suites
- 18-0217 Clearance for Lavatory
- 18-0218 Top Plates for Wood Stud Loadbearing Walls
- 18-0219 Multiple Transitions from ABS to PVC Piping in a Drainage System
- 18-0220 Dampproofing of Foundation Wall below Ground Level
- 18-0222 Glazed Wall Acting as a Guard
- 18-0223 Height of Handrails
- 18-0226 Braced Wall Panel at Porch with 2 Open Sides
- 18-0227 Fire Blocking at junction of Floor and Vertical Fire Separation

### 6.4 BCBC Errata or Revisions

- None to report

### 6.5 BSSB Technical Bulletins

None to report

# (7) ROUND TABLE DISCUSSION

- How other Building Departments in other Regional Districts are reacting to the *Fire Safety Act* replacing the *Fire Services Act*. RD's will soon be required to conduct Fire Safety audits like Municipalities, and some seem to think that the responsibility should fall on the Building Inspectors.

# (8) MEETING REVIEW

- Confirm the next meeting date.
- Three (3) CPD points will automatically be uploaded to your member profile when you register.

# (9) ADJOURNMENT (no motion required)

(Colin)

(All)

(Colin)