

BOABC SOUTH CENTRAL INTERIOR ZONE MEETING MINUTES Time: 1:00pm – 4:00pm Date: February 14, 2023

Living and working with gratitude and respect on the ancestral, unceded, and un-surrendered territories of Indigenous peoples in British Columbia.

(2) GUESTS (no motion required)

- Noah Quastel, Director, Law and Policy, Healthy Indoor Environments, BC Lung Foundation
- Chantal Wilson, P.Eng, Falcon Engineering
- Tyler Wightman, Executive Director & Registrar, BOABC

(3) AGENDA (requires motion to adopt)

Motion: adopt the agenda for February 14, 2023, as presented.

Mover: Laura Miller Seconder: Marc Vere

(4) PREVIOUS MINUTES (requires motion to adopt) (Tania)

Motion: adopt the minutes and the action items from the September 20, 2022, Zone meeting as presented.

Mover: Marc Vere Seconder: Jason Stoll

(5) NEW BUSINESS (no motion required)

5.1 Radon and the BC Building Code: Assessing Implementation

Presented on the health effects of radon gas exposure and what radon is. Explained how radon enters a house and how being exposed to high levels of radon can increase the risk of developing cancer, it is the second leading cause of lung cancer after smoking. Accurate radon testing can help prevent deaths.

Building Officials' Association of BC Suite 224, 186 – 8120 No. 2 Road, Richmond, BC V7C 5J8 604-270-9516 / info@boabc.org www.boabc.org (Tania)

(Tania)



5.2 Alternate Zone Director Nominations

(Tony)

- Tony discussed the importance of alternate zone directors. Nominations will be accepted until March 28, 2023.

5.3 What to Expect from BOABC in 2023

- Tyler Wightman, Executive Director, presented 2023 priorities: including Association Governance, 2023-26 Planning, Relationships, Education, Professionalism, and the 2022 Member Survey.

(6) STANDING AGENDA ITEMS (no motion required)

(Tania)

6.1 BOABC Calendar of Events

- CPD Offering Energy Step Code Training
- CPD Offering <u>Reducing Warranty Claims</u>
- CPD Offering Building Envelope Course
- CPD Offering Primary Changes to the 2020 National Model Codes
- BOABC Spring Conference & AGM, Richmond, BC, May 28-31, 2023

6.2 BC Appeal Board Rulings

- Appeal 1878 Exposure Protection for Required Egress Door Exterior Path of Travel, February 17, 2022
- <u>Appeal 1880</u> Required guard protection at intersection of deck and sloped roof, February 17, 2022
- <u>Appeal 1882</u> Minimum Room Size for a Water-Closet Room (Powder Room), March 17, 2022
- <u>Appeal 1883</u> Minimum Doorway Size for Water-Closet Room (Powder Room), March 17, 2022
- <u>Appeal 1884</u> Reduction of required doorway width and obstruction of access to the doorway March 17, 2022
- <u>Appeal 1885</u> Application of Building Code for Fabric Cover Yurts, April 28, 2022
- Appeal 1886 Location of Required Water Closets, April 28, 2022
- <u>Appeal 1887</u> Continuity of Required Fire Separation for a Secondary Suite, April 28, 2022
- Appeal 1890 Attic Access for Self-Storage Units, June 16, 2022
- <u>Appeal 1892</u> Fire Extinguishing for a Distillery, August 18, 2022
- <u>Appeal 1893</u> Required Fire Blocking, July 21, 2022
- Appeal 1894 Source of Water Supply for NFPA 13 Sprinkler Requirements, September 15, 2022
- **Appeal 1895** Use of Long Sweep degree Elbows in a Sanitary Drainage System, August 18, 2022

Building Officials' Association of BC

Suite 224, 186 – 8120 No. 2 Road, Richmond, BC V7C 5J8 604-270-9516 / info@boabc.org www.boabc.org



Appeal 1896 Required Fire Blocking, September 15, 2022

6.3 <u>BC Building Code Interpretations</u>

- 18-0196 Connection of Sewage Sump Vent to Other Pipes in a Venting System
- 18-0197 Vents for Oil Interceptors Connected to a Storm Drainage System
- 18-0199 Structural Design of Guards in Part 9 Buildings
- 18-0200 Positioning of Bottom Edge of Vision Panel at Doors
- 18-0201 Wireless Interconnection of Smoke Alarms
- 18-0202 Spiral Stair for Basement Storage Unit
- 18-0203 <u>Ramp Design</u>
- 18-0206 Permanent Label
- 18-0207 Exit Exposure Protection Without a Stair or Ramp
- 18-0209 Rainwater Leaders Connecting to a Dry Well
- 18-0210 Fire Blocks in Walls with Minor Combustible Components
- 18-0212 Continuous Illumination for Emergency Lighting
- 18-0213 Membrane Ceiling used as a Fire Separation
- 18-0214 <u>Door Swing</u>
- 18-0215 Exit Width Reduction at Door Swings
- 18-0216 Occupant Load of Residential Suites
- 18-0217 Clearance for Lavatory
- 18-0218 Top Plates for Wood Stud Loadbearing Walls
- 18-0219 Multiple Transitions from ABS to PVC Piping in a Drainage System
- 18-0220 Dampproofing of Foundation Wall below Ground Level
- 18-0221 Emergency Roof Overflows (Scuppers)
- 18-0222 Glazed Wall Acting as a Guard
- 18-0223 <u>Height of Handrails</u>
- 18-0226 Braced Wall Panel at Porch with 2 Open Sides
- 18-0227 Fire Blocking at junction of Floor and Vertical Fire Separation
- 18-0228 Parcel Lockers in Residential Lobbies
- 18-0229 Bottle Traps

6.4 BCBC Errata or Revisions

- None to report

6.5 BSSB Technical Bulletins

- None to report

(7) ROUND TABLE DISCUSSION

- Tania congratulated new RBO's
- Ken brought up Lunch & Learns & Secondary Suites

Building Officials' Association of BC Suite 224, 186 – 8120 No. 2 Road, Richmond, BC V7C 5J8 604-270-9516 / info@boabc.org www.boabc.org (All)



- How have municipalities been interpreting requirements for multi-family buildings where only a small portion of each unit is located over top of the neighboring dwelling? What if the multi-family contained a suite?

ie: Application of spatial separation 9.10.14 between buildings or 9.10.15 between houses.

- a. 9.10.14.1(1) This subsection applies to buildings other than those to which subsection 9.10.15 applies.
- b. 9.10.15.1(a) buildings that contain only dwelling units and have no dwelling unit above another dwelling unit.

(8) MEETING REVIEW

- Next meeting April 11, 2023
- Three (3) CPD points will automatically be uploaded to your member profile when you register.

(9) ADJOURNMENT (no motion required)

- The meeting was adjourned at 3:45pm

(Tania)

(Tania)

Building Officials' Association of BC Suite 224, 186 – 8120 No. 2 Road, Richmond, BC V7C 5J8 604-270-9516 / info@boabc.org www.boabc.org