

BOABC SOUTH CENTRAL INTERIOR ZONE MEETING AGENDA

Time: 1:00pm – 4:00pm Date: September 14, 2023

Living and working with gratitude and respect on the ancestral, unceded, and un-surrendered territories of Indigenous peoples in British Columbia.

(1) CALL TO ORDER

(Zone Director)

I would like to begin by acknowledging the ancestral, traditional, and unceded territories of Indigenous peoples in British Columbia, on whose territory we are today.

- (2) GUESTS (no motion required)
 - Andrew Kidd, Manager Prevention Field Services, WorkSafeBC
 - Andrew Cole, Executive Director, CUFCA
 - James Reid, Relationship Manager, Standards Education & Services, CSA Group
 - Dwayne Torrey, Director of Construction & Infrastructure Standards, CSA Group
 - Lauro Pilla, Program Manager, Construction & Infrastructure Standards, CSA Group
- (3) AGENDA (requires motion to adopt)

(Zone Director)

(4) PREVIOUS MINUTES (requires motion to adopt)

(Zone Director)

(5) NEW BUSINESS (no motion required)

(Zone Director)

- 5.1 Worksafe BC Presentation @ 1:10pm
- Andrew Kidd
- 5.2 Sprayed Polyurethane Foams in Construction Presentation @ 2:00pm
- Andrew Cole
- 5.3 Update on CSA Standards @ 3:00pm
 - James Reid
- Dwayne Torrey
- Lauro Pilla
- (6) STANDING AGENDA ITEMS (no motion required)

(Zone Director)

6.1 BOABC Calendar of Events



6.2 BC Appeal Board Rulings

- Appeal 1878 Exposure Protection for Required Egress Door Exterior Path of Travel, February 17, 2022
- Appeal 1894 <u>Source of Water Supply for NFPA 13 Sprinkler Requirements,</u> <u>September 15, 2022</u>
- Appeal 1895 <u>Use of Long Sweep degree Elbows in a Sanitary Drainage System,</u>
 August 18, 2022
- Appeal 1896 Required Fire Blocking, September 15, 2022

6.3 BC Building Code Interpretations

- 18-0131 Principal Entrance and Access Route
- 18-0228 Parcel Lockers in Residential Lobbies
- 18-0229 Bottle Traps
- 18-0230 <u>Sliding Doors</u>
- 18-0232 Fire Separation Between a Horizontal Service Space & the Floor Area Below
- 18-0233 Clearance of Cladding above Finished Ground
- 18-0236 Janitors' Room Fire Separation
- 18-0237 Party Wall in a Detached Garage Serving Two Single Family Dwelling Units
- 18-0239 Flashing
- 18-0240 Connection of a Radon Vent to Plumbing System Vent
- 18-0242 Mechanical Pressurization of Carbon Monoxide Vestibule
- 18-0243 Stair Handrail Extension
- 18-0245 Braced Wall Panels for Covered Deck
- 18-0247 Continuity of Vertical Fire Separations in Row Housing
- 18-0249 Inverted Roof Slope
- 18-0250 Fill under Small Garage Concrete Slab
- 18-0252 Reduction in Foundation Wall Thickness
- 18-0256 Combustible Outlet Boxes in Fire-rated Wall
- 18-0257 Measurement of 1.8 m Vestibule
- 18-0259 Supervision of Valves Controlling Water Supply in a Standpipe System
- 18-0263 Panic Hardware
- 18-0265 Use of Containers as a Building for Storage
- 18-0266 Cantilevered Roof Trusses and their Impact on Supporting Structure
- 18-0267 Responsibility for Firestopping of Sprinkler Pipe Penetrations
- 18-0268 Rainscreen Capillary Break Venting

6.4 BCBC Errata or Revisions

None to report



6.5 **BSSB Technical Bulletins**

- B23-03 Zero Carbon Step Code
- B23-02 <u>9.36.1.3. Compliance Paths</u>
- B23-01 Information for Planners about 20% Better Energy Efficiency and Zero Carbon Step Code
- (7) ROUND TABLE DISCUSSION

(All)

(8) MEETING REVIEW

(Zone Director)

- Confirm the next meeting date.
- Three (3) CPD points will automatically be uploaded to your member profile when you register.
- (9) ADJOURNMENT (no motion required)

(Zone Director)