

BOABC SOUTH CENTRAL INTERIOR ZONE MEETING MINUTES

Time: 1:00pm – 4:00pm Date: September 14, 2023

Living and working with gratitude and respect on the ancestral, unceded, and un-surrendered territories of Indigenous peoples in British Columbia.

(1) CALL TO ORDER

(Zone Director)

I would like to begin by acknowledging the ancestral, traditional, and unceded territories of Indigenous peoples in British Columbia, on whose territory we are today.

(2) GUESTS (no motion required)

- Andrew Kidd, Manager Prevention Field Services, WorkSafeBC
- Andrew Cole, Executive Director, CUFCA
- James Reid, Relationship Manager, Standards Education & Services, CSA Group
- Dwayne Torrey, Director of Construction & Infrastructure Standards, CSA Group
- Lauro Pilla, Program Manager, Construction & Infrastructure Standards, CSA Group

(3) AGENDA (requires motion to adopt)

(Zone Director)

Motion: adopt the agenda for September 14, 2023, as presented.

Mover: Ivo Tanner Seconder: Grant Trask

(4) PREVIOUS MINUTES (requires motion to adopt)

(Zone Director)

Motion: adopt the minutes and the action items from the April 17, 2023, Zone meeting as presented.

Mover: Adam Roja Seconder: Grant Trask

(5) NEW BUSINESS (no motion required)

(Zone Director)

5.1 Structural Stability - Stairs

- Presentation on how to prevent stair collapse, using the risk management basics approach.



5.2 BOABC Update

- Tyler Wightman

5.3 Sprayed Polyurethane Foams in Construction Presentation

Reviewed how to identify the main category of types of foam products encountered in
the field, the differences between half pound open cell foams and two-pound closed
cell foam systems, building code references with respect to use, application, field
quality conformity requirements. Also reviewed the fundamental elements of a
functioning Site Quality Assurance Program (SQAP) and explain why this is so important
to ensure property installed SPF products are inspected to protect building owners and
occupants.

5.4 Update on CSA Standards

- Introduction to Standards development, research, education, and advocacy: Implementing the 6 key areas of focus for CSA's Construction and Infrastructure team. Access for BC Building Officials: Custom collection of standards, subscription access, quick user guide and key takeaways.

(6) STANDING AGENDA ITEMS (no motion required)

(Zone Director)

6.1 BOABC Calendar of Events

6.2 BC Appeal Board Rulings

- Appeal 1878 <u>Exposure Protection for Required Egress Door Exterior Path of Travel,</u>
 <u>February 17, 2022</u>
- Appeal 1894 <u>Source of Water Supply for NFPA 13 Sprinkler Requirements,</u> September 15, 2022
- Appeal 1895 <u>Use of Long Sweep degree Elbows in a Sanitary Drainage System,</u>
 August 18, 2022
- Appeal 1896 Required Fire Blocking, September 15, 2022

6.3 BC Building Code Interpretations

- 18-0131 Principal Entrance and Access Route
- 18-0228 Parcel Lockers in Residential Lobbies
- 18-0229 Bottle Traps
- 18-0230 Sliding Doors
- 18-0232 Fire Separation Between a Horizontal Service Space & the Floor Area Below
- 18-0233 Clearance of Cladding above Finished Ground
- 18-0236 Janitors' Room Fire Separation
- 18-0237 Party Wall in a Detached Garage Serving Two Single Family Dwelling Units

Building Officials' Association of BC Suite 224, 186 – 8120 No. 2 Road, Richmond, BC V7C 5J8 604-270-9516 / info@boabc.org www.boabc.org



- 18-0239 Flashing
- 18-0240 Connection of a Radon Vent to Plumbing System Vent
- 18-0242 Mechanical Pressurization of Carbon Monoxide Vestibule
- 18-0243 Stair Handrail Extension
- 18-0245 Braced Wall Panels for Covered Deck
- 18-0247 Continuity of Vertical Fire Separations in Row Housing
- 18-0249 Inverted Roof Slope
- 18-0250 Fill under Small Garage Concrete Slab
- 18-0252 Reduction in Foundation Wall Thickness
- 18-0256 Combustible Outlet Boxes in Fire-rated Wall
- 18-0257 Measurement of 1.8 m Vestibule
- 18-0259 <u>Supervision of Valves Controlling Water Supply in a Standpipe System</u>
- 18-0263 Panic Hardware
- 18-0265 Use of Containers as a Building for Storage
- 18-0266 Cantilevered Roof Trusses and their Impact on Supporting Structure
- 18-0267 Responsibility for Firestopping of Sprinkler Pipe Penetrations
- 18-0268 Rainscreen Capillary Break Venting

6.4 BCBC Errata or Revisions

None to report

6.5 BSSB Technical Bulletins

- B23-03 Zero Carbon Step Code
- B23-02 9.36.1.3. Compliance Paths
- B23-01 <u>Information for Planners about 20% Better Energy Efficiency and Zero Carbon Step Code</u>

(7) ROUND TABLE DISCUSSION

(All)

None

(8) MEETING REVIEW

(Zone Director)

- Next meeting date TBD
- Three (3) CPD points will automatically be uploaded to your member profile when you register.

(9) ADJOURNMENT (no motion required)

(Zone Director)

- The meeting was adjourned at 4:00pm