



BOABC CENTRAL NORTHERN INTERIOR ZONE MEETING MINUTES

Time: 1:00pm – 4:00pm

Date: February 23, 2023

Living and working with gratitude and respect on the ancestral, unceded, and un-surrendered territories of Indigenous peoples in British Columbia.

- (1) **CALL TO ORDER @ 1:01pm** (Blaine)
I would like to begin by acknowledging the ancestral, traditional, and unceded territories of Indigenous peoples in British Columbia, on whose territory we are today.

- (2) **GUESTS (no motion required)**
- Noah Quastel, Director, Law and Policy, Healthy Indoor Environments, BC Lung Foundation
 - Chantal Wilson, P.Eng, Falcon Engineering
 - Tyler Wightman, Executive Director & Registrar, BOABC

- (3) **AGENDA (requires motion to adopt)** (Blaine)

Motion: adopt the agenda for February 23, 2023, as presented.

Mover: Lynn Berlin

Seconder: Sean O'Shaughnessy

- (4) **PREVIOUS MINUTES (requires motion to adopt)** (Blaine)

Motion: adopt the minutes and the action items from the September 26, 2022, Zone meeting as presented.

Mover: Bill Darnbrough

Seconder: Rick Hodgson

- (5) **NEW BUSINESS (no motion required)** (Blaine)

5.1 Radon and the BC Building Code: Assessing Implementation

- Presented on the health effects of radon gas exposure and what radon is. Explained how radon enters a house and how being exposed to high levels of radon can increase the risk of developing cancer, it is the second leading cause of lung cancer after smoking. Accurate radon testing can help prevent deaths.



5.2 Zone Director/Alternate Zone Director Nominations

(Tony)

- Tony discussed the importance of alternate zone directors. Nominations will be accepted until March 28, 2023.
- Jason Berlin put his name forward again for alternate zone director.

5.3 What to Expect from BOABC in 2023

- Tyler Wightman, Executive Director, presented 2023 priorities: including Association Governance, 2023-26 Planning, Relationships, Education, Professionalism, and the 2022 Member Survey.

(6) STANDING AGENDA ITEMS (no motion required)

(Blaine)

6.1 [BOABC Calendar of Events](#)

- CPD Offering [Energy Step Code Training](#)
- CPD Offering [Reducing Warranty Claims](#)
- CPD Offering [Building Envelope Course](#)
- CPD Offering [Primary Changes to the 2020 National Model Codes](#)
- [BOABC Spring Conference & AGM, Richmond, BC, May 28-31, 2023](#)

6.2 [BC Appeal Board Rulings](#)

- **Appeal 1878** Exposure Protection for Required Egress Door Exterior Path of Travel, February 17, 2022
- [Appeal 1880](#) Required guard protection at intersection of deck and sloped roof, February 17, 2022
- [Appeal 1882](#) Minimum Room Size for a Water-Closet Room (Powder Room), March 17, 2022
- [Appeal 1883](#) Minimum Doorway Size for Water-Closet Room (Powder Room), March 17, 2022
- [Appeal 1884](#) Reduction of required doorway width and obstruction of access to the doorway – March 17, 2022
- [Appeal 1885](#) Application of Building Code for Fabric Cover Yurts, April 28, 2022
- [Appeal 1886](#) Location of Required Water Closets, April 28, 2022
- [Appeal 1887](#) Continuity of Required Fire Separation for a Secondary Suite, April 28, 2022
- [Appeal 1890](#) Attic Access for Self-Storage Units, June 16, 2022
- [Appeal 1892](#) Fire Extinguishing for a Distillery, August 18, 2022
- [Appeal 1893](#) Required Fire Blocking, July 21, 2022
- **Appeal 1894** Source of Water Supply for NFPA 13 Sprinkler Requirements, September 15, 2022



- **Appeal 1895** Use of Long Sweep degree Elbows in a Sanitary Drainage System, August 18, 2022
- **Appeal 1896** Required Fire Blocking, September 15, 2022

6.3 **BC Building Code Interpretations**

- 18-0196 [Connection of Sewage Sump Vent to Other Pipes in a Venting System](#)
- 18-0197 [Vents for Oil Interceptors Connected to a Storm Drainage System](#)
- 18-0199 [Structural Design of Guards in Part 9 Buildings](#)
- 18-0200 [Positioning of Bottom Edge of Vision Panel at Doors](#)
- 18-0201 [Wireless Interconnection of Smoke Alarms](#)
- 18-0202 [Spiral Stair for Basement Storage Unit](#)
- 18-0203 [Ramp Design](#)
- 18-0206 [Permanent Label](#)
- 18-0207 [Exit Exposure Protection Without a Stair or Ramp](#)
- 18-0209 [Rainwater Leaders Connecting to a Dry Well](#)
- 18-0210 [Fire Blocks in Walls with Minor Combustible Components](#)
- 18-0212 [Continuous Illumination for Emergency Lighting](#)
- 18-0213 [Membrane Ceiling used as a Fire Separation](#)
- 18-0214 [Door Swing](#)
- 18-0215 [Exit Width Reduction at Door Swings](#)
- 18-0216 [Occupant Load of Residential Suites](#)
- 18-0217 [Clearance for Lavatory](#)
- 18-0218 [Top Plates for Wood Stud Loadbearing Walls](#)
- 18-0219 [Multiple Transitions from ABS to PVC Piping in a Drainage System](#)
- 18-0220 [Dampproofing of Foundation Wall below Ground Level](#)
- 18-0221 [Emergency Roof Overflows \(Scuppers\)](#)
- 18-0222 [Glazed Wall Acting as a Guard](#)
- 18-0223 [Height of Handrails](#)
- 18-0226 [Braced Wall Panel at Porch with 2 Open Sides](#)
- 18-0227 [Fire Blocking at junction of Floor and Vertical Fire Separation](#)
- 18-0228 [Parcel Lockers in Residential Lobbies](#)
- 18-0229 [Bottle Traps](#)

6.4 **BCBC Errata or Revisions**

- None to report

6.5 **BSSB Technical Bulletins**

- None to report



- (7) **ROUND TABLE DISCUSSION** (All)
- Wildfire Bylaw – Fire rating from outside to inside. Barrier Tech. product used.
 - Secondary Suites – Fire dampers required where penetrations through fire separation. Separate heating controls.
 - Prescriptive Requirements:
 - Went over min order M40, specifically section 2.2(4) where a L.G. enacts the ability to use 9.36.2 to 9.36.4 (presc. methods).
 - Do log homes need enactment to use 9.36.2 to 9.36.4.
- (8) **MEETING REVIEW** (Blaine)
- Next meeting April 27, 2023.
 - Three (3) CPD points will automatically be uploaded to your member profile when you register.
- (9) **ADJOURNMENT (no motion required)** (Blaine)
- The meeting was adjourned at 3:58pm