

2024 BC Building Code – LIST OF REVISIONS – Accessibility

Code Reference	TYPE OF CHANGE				
	Editorial	Relocated	New	Comments	
	•			•	
		Di	ivision B - Pa Section 9.5		
9.5.2.1.(1)	✓			Exceptions to Accessibility requirements found in the additional 9.5.2.3. and the existing 3.8.2.1.	
9.5.2.2.(1)	✓			Now allows for an exemption to accessibility requirements for the first storey.	
9.5.2.3.		✓		Moves apartment building accessibility exceptions from 3.8.2 to 9.5.2.3.	
9.5.2.4.			✓	New to BCBC. Visible Signal Devices to conform to 3.2.4.19. and 3.2.4.20.	
9.5.2.5.			✓	New to BCBC. Lighting to also conform to 3.2.7.1.	
9.5.3.1.(2)		✓		Moves ceiling height for secondary suite from (Table 1.1.1.1. in Division A).	
9.5.3.1.(3)		✓		Moves clear height below beams and ducts for secondary suite from (Table 1.1.1.1. in Division A).	
		Di	ivision B - Pa Section 9.8		
9.8.1.5.(1)			✓	New requirement for tactile warning indicators to meet 3.3.1.19.	
9.8.4.9.			✓	New restrictions on open stairs.	
9.8.6.2.	✓			Adding reference to explanatory note.	
9.8.8.1.	✓			Adding better clarification on guard requirements.	
9.8.8.2.	✓			Revised wording to include a requirement for guard structural resistance.	
9.8.8.3.(1)	✓			Revised wording to include sentence 2 to the exception.	
9.8.8.5.(2)	✓			Revised wording to clarify openings at the bottom of guards and stairs.	
9.8.8.7.	✓			Correcting standard reference name.	
9.8.9.5.(1)	✓			Revised wording.	

www.boabc.org 1



2024 BC Building Code - LIST OF REVISIONS - Accessibility

CZ+ BO Bananig	-		11210	710110 7100030151111ty 40°1°	
Code Reference	TYPE OF CHANGE				
	Editorial	Relocated	New	Comments	
A-9.8.6.2.(2)			✓	A door that swings away from a stair exposes sufficient floor space to act as a landing for users before descending the stairs.	
A-9.8.8.1.			✓	Added figure A-9.8.8.1.	
A-9.8.8.1.(4)	✓			Changes to window fall protection.	
Division B - Part 9 Section 9.9					
9.9.6.4.(5)(c)(i)	✓			Larger storage units permitted to have overhead doors.	
9.9.6.7.(3)	✓			New requirement for the minimum height of door release hardware to ensure the hardware is not installed too low.	
9.9.11.3			√	Additions to Sentences (1) and (2) and Sentence (7) to align Part 9 with Part 3 of the NBC 2020 for visual and tactile information on signs.	

www.boabc.org 2