

## **BOABC SOUTH CENTRAL INTERIOR ZONE MEETING AGENDA**

Time: 1:00pm – 4:00pm Date: January 16, 2024

Living and working with gratitude and respect on the ancestral, unceded, and un-surrendered territories of Indigenous peoples in British Columbia.

(1) CALL TO ORDER (Zone Director)

I would like to begin by acknowledging the ancestral, traditional, and unceded territories of Indigenous peoples in British Columbia, on whose territory we are today.

- (2) GUESTS (no motion required)
  - Gord Rattray, Manufactured Housing Association of BC (MHABC)
  - Sukh Johal, Western Wood Truss Association
  - David Hunt, Senior Vice President, Archistar
- (3) AGENDA (requires motion to adopt) (Zone Director)
- (4) PREVIOUS MINUTES (requires motion to adopt) (Zone Director)
- (5) NEW BUSINESS (no motion required) (Zone Director)
  - 5.1 MHABC and Western Wood Truss Association @ 1:10pm
    - Gord Rattray
  - Sukh Johal
  - 5.2 Practical uses of AI in the Building Permit Assessment Process @ 2:00pm
  - David Hunt
  - **5.3 Zone Director / Alternate Nominations**
- (6) STANDING AGENDA ITEMS (no motion required) (Zone Director)
  - **6.1 BOABC Calendar of Events**
  - **6.2 BC Appeal Board Rulings** 
    - None to report



## **6.3 BCBC Errata or Revisions**

- None to report

## **6.4** BSSB Technical Bulletins

- None to report

## **6.5 BC Building Code Interpretations**

- 18-0253 Fire Separation of a Service Room in a House with a Secondary Suite
- 18-0271 Floor Drain Requirements for a Basement
- 18-0272 Fire Department Access to Cut-off Portions of a Building
- 18-0273 Wind Loads on Roofing Membranes
- 18-0274 Fire Separation between a Garbage or Recycling Room and a Storage Garage
- 18-0276 Sign affixed to a Building
- 18-0279 Use of 90-degree Elbow to join two Soil-or-Waste Pipes
- 18-0280 Insulation of Domestic Hot Water Recirculation Piping
- 18-0281 Testing of Drainage Pipes in a Storm Drainage System
- 18-0282 <u>Seismic Restraint for Pendant Lights</u>
- 18-0284 Townhouse Exterior Exit on Vehicle Access Route
- 18-0287 Fire Rating for Wood Frame Assemblies
- 18-0289 Normal & Emergency Lighting for Exterior Exits

/ <b>7</b> \	ROUND TABLE DISCUSSION		/ A II )
.,,	ROUND IABLE DISCUSSION		I AIII

(8) MEETING REVIEW (Zone Director)

(9) ADJOURNMENT (no motion required) (Zone Director)